

bikethewoodlands.org

Road Shoulder Hazards in The Woodlands – January 2015


Definition of hazard types:

- **1. Lip:** lip protruding for several feet at least 1 inch above adjacent pavement
- 2. Gap: gap extending for several feet, in which bike tire could fall into
- **3. Pothole:** hole that should be filled
- 4. Rough area: excessively rough area the should be fixed
- **5. Maintenance:** not a danger to cyclists but something the county might want to be aware of
- 6. Other: items that don't fall into the above


Severity ratings

- Level 4 A serious and immediate danger to cyclists
- Level 3 Should be fixed soon; could be a danger
- Level 2 Potential hazard to note, but not very serious
- Level 1 Not hazard to cyclists, but something that the county might want to be aware of

Road Shoulder Hazards in The Woodlands – January 2015



Road Shoulder Hazards in The Woodlands – January 2015 Levels 3 and 4 only



Hazards by road

		Hazard level:				
	Distance, mi	1	2	3	4	Total
Branch Crossing	3.51	1	5	4	1	11
Cochrans Crossing	3.26		2	9	8	19
Flintridge	3.46		5	5	7	17
Lake Woodlands	6.08	8	7	18	6	39
North Panther Creek	1.25		1	3	4	8
Shadowbend	1.86	1	24	12	6	43
Shadowbend pathway	2.61		12	1		13
Sterling Ridge	1.86		3			3
Terramount	2.31		1	2		3
West Panther Creek	0.98			12	1	13
Woodlands Parkway (West)	2.61		7			7
Woodlands Parkway pathway	0.94		1	2	1	4
	30.73	10	68	68	34	180

Distance is distance surveyed.

• The following slides show some examples.

LW-7 Lake Woodlands Westbound Hazard type: Pothole Severity: 4 Serious pothole



IMG_0772

LW-15 Lake Woodlands Westbound Hazard type: Rough area and Pothole Severity: 3





LW-20 Lake Woodlands Eastbound

Hazard type: Rough area Severity: 3 Shoulder deterioration leading to narrower-thanexpected shoulder.



Location WP 6 Woodlands Pkwy Eastbound Hazard Type: Pothole Severity: 2 6" wide gouge in the shoulder over 4 feet long which cyclists tire could get stuck in and cause bike to fall. Unlike Flintridge, Shoulder is wider on this stretch of and cyclists are able to ride to the right of the damaged shoulder comfortably if they see the pot hole in time.



Location Sh-13 Shadowbend Northbound

Hazard Type: Pothole Severity: 4 3.5" drop from road surface to shoulder at intersection with LW Photo 1



WP_20141230_012


Location Sh-20 Shadowbend Northbound

Hazard Type: Lip Severity: 3

Eroded Section from Roadway 1.5" deep-Photo 1



Location Sh-22 Shadowbend Northbound Hazard Type: Maint. Severity: 2 Degraded shoulder edge due to car parking near Collins Intermediate School



WP_20141230_022

WP_20141230_022.jpg

Location Sh-27 Shadowbend Southbound Hazard Type: Other Severity: 2 Sewer Structure 1" above shoulder




WP_20141230_027

Location Sh-31a Shadowbend Southbound Hazard Type: Other Severity: 2 Degraded Edge near Intersection with LW



WP_20141230_001

Location WPC-3 West Panther Creek Southbound Hazard Type: Rough area; lip Severity: 4 Poorly repaired shoulder over more than 50 feet coupled with gap and 2 inch lip



IMG_3651

Location WPC-5 West Panther Creek Southbound Hazard Type: Rough area Crumbled shoulder with exposed large rocks Severity: 3



Location WPC-6 West Panther Creek Southbound Hazard Type: Rough area Close up of IMG3588 shoulder area Severity: 3



Location NPC-3 North Panther Creek Northbound Hazard Type: Gap; Lip Severity: 4 Large, deep gap 15 to 20 feet in legnth

