# Road Shoulder Hazards along <a href="Sterling Ridge">Sterling Ridge</a> – January 2015

Hazards on road shoulders, that could pose a risk to cyclists, were identified in January 2015 by volunteers from Bike The Woodlands Coalition.

The interpretation of what constitutes a serious hazard is subjective, and may vary between volunteers.

### Definition of hazard types:

- 1. **Lip:** lip protruding for several feet at least 1 inch above adjacent pavement
- **2. Gap:** gap extending for several feet, in which bike tire could fall into
- 3. Pothole: hole that should be filled
- 4. Rough area: excessively rough area the should be fixed
- **5. Maintenance:** not a danger to cyclists but something the county might want to be aware of
- **6. Other:** items that don't fall into the above

## Severity ratings

- Level 4 A serious and immediate danger to cyclists
- Level 3 Should be fixed soon; could be a danger
- Level 2 Potential hazard to note, but not very serious
- Level 1 Not hazard to cyclists, but something that the county might want to be aware of

#### Hazards by road

		Hazard level:				
	Distance, mi	1	2	3	4	Total
Branch Crossing	3.51	1	5	4	1	11
Cochrans Crossing	3.26		2	9	8	19
Flintridge	3.46		5	5	7	17
Lake Woodlands	6.08	8	7	18	6	39
North Panther Creek	1.25		1	3	4	8
Shadowbend	1.86	1	24	12	6	43
Shadowbend pathway	2.61		12	1		13
Sterling Ridge	1.86		3			3
Terramount	2.31		1	2		3
West Panther Creek	0.98			12	1	13
Woodlands Parkway (West)	2.61		7			7
Woodlands Parkway pathway	0.94		1	2	1	4
	30.73	10	68	68	34	180

Distance is distance surveyed.

#### Sterling Ridge Hazard Locations



Location SR-1 Sterling Ridge Westbound Hazard Type: Rough Area

Severity: 2

Rough area causing cyclists to move on to road if possible.



IMG\_2391

Location SR-2 Sterling Ridge Eastbound Hazard Type: Rough Area

Severity: 2

Vegetation is starting to penetrate the

perimeter of the patch.



IMG\_2372

Location SR-3 Sterling Ridge Eastbound Hazard Type: Rough Area

Severity: 3



IMG\_2374